

COASTAL AQUACULTURE AUTHORITY


ADVISORY NOTICE

ATTENTION : HATCHERY OWNERS / OPERATORS

During CAA inspection of hatcheries including Nauplii Rearing Centres, it has been observed that hatcheries are not operating as per CAA Act and Guidelines. The following deficiencies have been observed :

- Absence of SHOWER AND CHANGE ROOM at each entry point of PLRT/LRT/Maturation units;
- No coverings on the drain canal in larval section;
- No mesh on windows / exhaust outlets in larval section;
- No functional PCR Laboratory;
- No proper Effluent Treatment System (ETS) depending on the volume of discharge water, positioning of inlet and outlet drain pipes;

FIGURE OF SHOWER ROOM



**COMPLIANCE OF THESE FACILITIES IS MANDATORY
AS PER CAA ACT 2005.**

Cgdm
13/06/18

MEMBER SECRETARY